TWIN BRIDGES

7/21/06



R-1, surface detail

R-1, overview



T-1, surface detail

T-1, overview

TWIN BRIDGES

7/21/06

A-1, overview with depression

A-1, overview

TWIN BRIDGES







PAVEMENT STRENGTH SURVEY/PAVEMENT CONDITION SURVEY

PAVE. IDENT.	SOIL CLASS	SUB GRADE CLASS	SUBBASE COURSE	BASE COURSE	SURFACE COURSE	OVERLAY	PAVEMENT STRENGTH MAX. GROSS LOAD (LBS) SINGLE	DUAL	DUAL TAN.	REMARKS
RUNWAYS										
R–1	CBR=5			11" P–208	P609	1.8" P–401	12,500			1 2
TAXIWAYS										
T–1	CBR=5			11" P–208	P609	1.8" P–401	12,500			1 2
APRONS										
A–1	CBR=5			11" P–208	P609	1.8" P–401	12,500			1 2
A–2				UNKNOWN	PCC		UNKNOWN			

REMARKS:

1 AIP–03, 1988, ALL NEW PAVEMENTS.

2 AIP–04, 2000, OVERLAY EXISTING BITUMINOUS RUNWAY, TAXIWAY, APRON, AND TURNAROUNDS.

LEGEND

- 1994 SURVEY AREA
- 1997 SURVEY AREA
- 2000 SURVEY AREA (NOT SURVEYED)
- 2003 SURVEY AREA
- 2006 SURVEY AREA

DATE OF PAVEMENT STRENGTH SURVEY:	
EVALUATED BY:	
DATE OF MOST RECENT PAVEMENT CONDITION SURVEY:	JULY 21, 2006
EVALUATED BY:	B. BURKLAND

MONTANA AVIATION SYSTEM PLAN
2006 UPDATE - PAVEMENT CONDITION INDEXES

TWIN BRIDGES AIRPORT

PREPARED FOR: MONTANA AERONAUTICS DIVISION

TWIN BRIDGES MONTANA

DATE: NOV. 2006

PREPARED BY: ROBERT PECCIA & ASSOCIATES

TWIN BRIDGES