PLANS
NOT
TO
SCALE

FED. ROAD DIST. NO.	STATE	FED. AID PROJ. NO.	FISCAL YEAR	SHEET NO	TOTAL SHEETS
8	Mont	N.R.S. 279		1	1

STA. 28+69.5 = STA. 29+48.5 E.A.P. 207A
BEGIN N.R.S. 279
of 0+00.0

℄ Front St. Paving

Frankie Lode Mineral Survey # 951

Montana St. ℄ Sta. 20+84.5 Bem 207A

Cont. Oil Co. Paved Driveway

Sta. 3+30 Cal. Imp. 52' C.M.P. Plant Hist. Drain. In place

Sta. 7+66.1 Rt. 12.4' C.M.P. Drain. In place

Sta. 10+87.1 Head Lt. Drain. In place

40' Radius curves to round off edge of pavement.

A.C.M. Co South of road

Largey Estate and Etta D. Mantle 799

Mary Ann Lode 154

Cor. #2 of Mary Ann

Cor. #1 of Mary Ann

Cor. #4 of Pikes Peak

Note - Maximum speed loaded and down incline M.P.H. All trains stop or derail.

Domestic Mang. & Development Co.

Conditate Col. Sp.

Sta. 21+25 - 15+25.0 C.M.P. Rt. 3' 1 Drain. In place

Sta. 22+15 - 19+22.5 C.M.P. Drain. In place

Sta. 24+65 - 12+47 Grass Pipe. Rt. App. Rt. In place.

Sta. 27+19 - 14+23 Deep Drain 18" C.M.P. Rt. In place. Skew.

Timber Bridge Warning Sign

EQUATION

EQUATION

M.E. 575 A.C.M. Co.

Brown's Burn Down

Brick house

Brick No. Brick No. Frame No.

Well

Brick No. Frame No.

Sta. 2+15 Rt. Rt. App. Rt. Pipe. In place.

Sta. 2+15 Rt. App. Rt. Pipe. In place.

Sta. 2+15 Rt. App. Rt. Pipe. In place.

Brick No. Frame No.

Garage Frank Bell Living Works

Office Yard

Garage New Storage Storage

Wood Yard

Brick No.

Garage Tile No.

Brick No. Frame No.

Cor. #4

Cor. #3

Cor. #2

Cor. #1

Cor. #4

Cor. #3

Cor. #2

Cor. #1

Cor. #4

Cor. #3

Cor. #2

Cor. #1